Illinois Commerce Commission Pipeline Safety Field Trip Report

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: Dallas Jett Total Man Days: 3						
Pipeline Safety Representative(s): Jim Watts						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	11/14/2013					

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Integrity Management Field Audit	Murphysboro	Jim Watts	Transmission			Dallas Jett, Gary Bowers, Ray Emmenderfer, Rodney Pinnon, Tim Ashenfelter

Statement of Activities

On September 17-19, 2013, Staff observed Transmission Integrity Direct Assessment (ICDA) inspections performed by Ameren Illinois in areas of High Consequence Areas (HCA) to determine if internal corrosion is present at locations where the pipeline is at an angle where liquids could drop out of the gas stream and collect. A total of 6 locations were inspected with 2 being north of Murphysboro, Illinois, on a 12 inch transmission line; 1 north of Carbondale, Illinois, on a 10 inch transmission line; 1 in Marion, Illinois, on a 10 inch transmission line; and 2 outside of Pittsburg, Illinois, on a 4 inch transmission line. The inspections observed were performed using guided wave with no indications of internal or external corrosion being detected. The individuals with Structural Integrity Associates (SIA) performed the guided wave tests using calibrated equipment. The personnel with SIA had documentation indicating their current qualifications for conducting guided wave.

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.